Geotechnical Requirements for Bridges

03

John Weeldreyer, PE Foundation Engineer Geotechnical Engineering Activity SD DOT

Geotechnical Requirements for Bridges

- Section 10.4 Soil and Rock Properties
 - Project requirements and site conditions
 - Resign and constructability
 - Rerformance criteria
 - Geologic & Hydrologic concerns

 - Methods to obtain parameters, number of tests/samples needed and locations for them

03

- Extent of exploration shall be based on:
 - variability in the subsurface conditions,
 - structure type,
 - Project requirements that may affect foundation design or construction.
- Shall be extensive enough to:
 - Reveal the nature and types of soil deposits and/or formations encountered,
 - CS Provide engineering properties, and
 - Groundwater conditions.

03

- ⊗ Borings shall be sufficient in number and depth to establish a reliable subsurface profile at areas of concern such as:
 - G Foundation locations, and
 - Adjacent earthwork locations.
 - Also to investigate any adjacent geologic hazards that could affect the structure performance.

03

- At a minimum subsurface exploration and testing program shall obtain information adequate to analyze foundation stability and settlement with respect to:
 - Geological formations present,
 - CS Location and thickness of soil and rock units,
 - Groundwater conditions, and
 - Local considerations

03

Single Span Deep

- One boring at each proposed abutment.
- Additional borings depending on project requirements.

Multiple Span Deep

- One boring at each proposed abutment.
- One boring at each proposed bent/pier...
 - calculate that is reachable depending on site conditions.



- Shallow Foundations
 - Minimum of one boring per substructure unit.
 - Will most likely need more than one boring to define limits of rock surface within footprint of footing.

Geotechnical Requirements for Bridges

- Hole plugging as per ARSD 74:11:08
- Geotechnical recommendations shall include a drivability analysis and recommend hammer sizes.
- Common Issues we have seen:
 - Insufficient boring depths for proposed foundation type/anticipated tips.
 - Insufficient data for slope stability analysis when required.

Any questions?





